

### State of Utah

# Department of Natural Resources

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:	
Company	David Shaver Manager	
OGM	Pete Hess Environmental Scientist III	

# **Inspection Report**

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, November 24, 2009
Start Date/Time:	11/24/2009 7:50:00 AM
End Date/Time:	11/24/2009 8:30:00 AM
Last Inspection:	Tuesday, October 27, 2009

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear, cold; 30's F.
InspectionID Report Number: 2206

Reprocessing

Accepted by: jhelfric

12/7/2009

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Total Disturbed
Phase I
Phase II
Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

100.00 Total Permitted

**Current Acreages** 

78.45

Mineral Ownership	Types of Operations		
✓ Federal	☐ Underground		
☐ State	Surface		
☐ County	✓ Loadout		
Fee	Y Processing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The DOGM water monitoring data base contains information for the third quarter of 2009 which needs to be uploaded. All four stream monitoring points (WCW1-4) and all six UPDES outfalls have been reported as having no flow for all three months of the third quarter. The Permittee continues to meet this Special Condition contained as Attachment "A" of the current State of Utah permit.

Other

Inspector's Signature:

\_

Date

Tuesday, November 24, 2009

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, November 24, 2009

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		<b>✓</b>	
2.	Signs and Markers	✓			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		V	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		<b>✓</b>		
6.	Disposal of Excess Spoil, Fills, Benches		<b>✓</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>V</b>			
8.	Noncoal Waste	<b>V</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		<b>✓</b>		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control		<b>V</b>		
15.	Cessation of Operations		✓		
16.a	Roads: Construction, Maintenance, Surfacing	✓		<b>V</b>	
16.b	Roads: Drainage Controls	<b>✓</b>			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	<b>✓</b>			
19.	AVS Check	✓		<b>✓</b>	
20.	Air Quality Permit				
21.	Bonding and Insurance				
	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, November 24, 2009

Page 3 of 3

# 1. Permits, Change, Transfer, Renewal, Sale

The review of the submitted information to address DO-04 is ongoing within the Division.

## 4.d Hydrologic Balance: Water Monitoring

All sediment ponds were dry; there was no flow in any of the adjacent area undisturbed channels.

# 16.a Roads: Construction, Maintenance, Surfacing

A pile of road material exists at the SE corner of pond "C". This accumulation is the result of snow removal at the site. The Permittee was asked to dispose of the material at the waste rock disposal site.

## 19. AVS Check

The Division understands that a new President and CEO has been temporarily appointed to fill the position at UtahAmerican Energy, Inc.